


ERA24LA234

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left horizontal stabilizer showing leading edge damage (Courtesy of FAA)



Photograph 2 - Close up view of damaged left horizontal stabilizer (Courtesy of FAA)