

ERA24LA238

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph. Rear View of the Inverted Airplane at the Accident Site



Photograph 2 - FAA Digital Photograph. Right Quartering View of the Right Side of the Fuselage and Portion of Right Wing. Note both Wing Lift Struts damaged



Photograph 3 - FAA Digital Photograph. Left Quartering View of the Left Side of the Fuselage and Portion of the Left Wing