

ERA24LA239

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at the accident site. (Courtesy of FAA)



Photograph 2 - View of the left side of the airplane. (Courtesy of FAA)



Photograph 3 - View of the tail and right wing of the airplane. (Courtesy of FAA)



Photograph 4 - View of the engine prior to teardown. (Courtesy of FAA)



Photograph 5 - View of the No. 2 cylinder rocker box cover with fractured parts. (Courtesy of FAA)



Photograph 6 - View of the No. 2 Cylinder with rocker box cover removed. (Courtesy of FAA)