

ERA22LA241

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Engine And Propeller (NTSB)



Photograph 3 - Carburetor (NTSB)



Photograph 4 - Top Spark Plugs (Courtesy of Lycoming)



Photograph 5 - Screenshot of Engine Run Video (Courtesy of FAA)