

ERA24LA242

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage overview (Courtesy of FAA)



Photograph 2 - Wreckage overview (Courtesy of FAA)



Photograph 3 - Main rotor assembly and drive shaft (Courtesy of FAA)



Photograph 4 - Drive belt pulley (Courtesy of FAA)



Photograph 5 - Tail rotor assembly (Courtesy of FAA)



Photograph 6 - Tail rotor assembly (Courtesy of FAA)



Photograph 7 - Tail rotor drive shaft (Courtesy of FAA)