

ERA24LA251

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the accident airplane at the accident site (Photo Courtesy of FAA)



Photo 2: View of the elevator connecting rod attachment area missing its hardware (Photo Courtesy of FAA)




Photo 3: View of the elevator connecting rod attachment areas, exemplar and accident airplane (Photo Courtesy of FAA & Just Aircraft)




Photo 4: Additional views of the accident airplane missing its elevator connecting rod hardware (screw and locknut) (Photo Courtesy of FAA)