

ERA24LA253


INVESTIGATION PHOTOGRAPHS




Photograph 1 - FAA Digital Photograph. Left Forward Quartering View of the Airplane Where it Came to Rest



Photograph 2 - FAA Digital Photograph. Right Forward Quartering View of the Airplane at the Accident Site.



Photograph 3 - FAA Digital Photograph. View of the Bottom of the Left Wing. Note the Chordwise Cracks in the Lower Wing



Photograph 4 - FAA Digital Photograph. View of the Outboard Upper Surface of the Left Wing. Note the Cracks



Photograph 5 - Digital Photograph From New Owner. View Showing the Broken Engine Mount Tubes