

ERA24LA257

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at the accident site (Source: FAA)



Photograph 2 - Airplane at accident site (Source: FAA)



Photograph 3 - Airplane after recovery



Photograph 4 - Damage to empennage



Photograph 5 - Debris found in strainer bowl



Photograph 6 - Debris found in strainer screen



Photograph 7 - Debris found in carburetor through drain plug




Photograph 8 - Corrosion and debris found in the carburetor bowl



Photograph 9 - Debris found in the carburetor main metering jet well



Photograph 10 - Debris found on the main metering jet



Photograph 11 - Debris found in carburetor mixture control sleeve



Photograph 12 - Sample of corroded debris found in the carburetor with scale



Photograph 13 - Fuel pump after disassembly



Photograph 14 - Fuel pump with corroded internal components (Source: Lycoming)



Photograph 15 - Fuel pump with corroded internal components (Source: Lycoming)