

ERA24LA258

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fractures noted to fuselage and right wing (Courtesy of FAA)



Photograph 2 - Fractures and partial separation noted to empennage (Courtesy of FAA)