

ERALA24259

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right aileron damage (Courtesy of FAA)



Photograph 2 - Right main landing gear collapse (Courtesy of FAA)