

ERA24LA270

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft postaccident (Courtesy of FAA)



Photograph 2 - Right Wing postaccident damage (Courtesy of FAA)



Photograph 3 - Left side postaccident damage (Courtesy of FAA)