

ERA24LA277

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to nose landing gear (Courtesy of FAA)



Photograph 2 - Deformation noted to engine mount (Courtesy of FAA)