

ERA24LA287

INVESTIGATION PHOTOGRAPH



Photograph 1 - Main Wreckage With Tailboom Damage (Courtesy of FAA)