

ERA24LA289

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left wing impact damage and aileron separation noted (Courtesy of FAA)



Photograph 2 - oil cooler obstructed with a residential-type insulation (Courtesy of FAA)



Photograph 3 - Residential-type insulation noted on nose landing gear (Courtesy of FAA)



Photograph 4 - Residential-type insulation noted in engine area (Courtesy of FAA)