

RECORD OF ☐ VISIT ☐ CONFERENCE OR ☒ TELEPHONE CALL		TIME 2:33 PM	DATE 07/22/2024
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION Captain: Charles Stanley Tippet Jr.		ROUTING	
		SYMBOL	INITIALS
SUBJECT N9581S, 7ECA, EXPERIENCED AN ENGINE FAILURE AND CRASHED NEAR THE			
INTERSECTION OF NC 101 AND JUNE MERRILL FARM ROAD.			
DIGEST 07/22/2024, 02:33 pm, I called the aircraft's pilot, Mr. Charles Stanley Tippet Jr., and he stated the following information over the phone. He is a CFI with over 9000 hours. Has been flying this aircraft for 15 years and made a similar flight 1000's of times out of his farm. Flying along and about 10 miles out the engine went down a little bit and then came back. Checked fuel said there was about 1/4 tank, and not worried because he could see the airport. A minute later the engine stutters again, and he then went full rich on mixture, and it came back. Again, he looked to verify fuel level. Then the engine quit about 4 miles from MRH airport. He looked around and decided to land on road since there were no cars. As soon as he touched down he hit a pole that spun him around and flipped him over. They both climbed out of the aircraft on their own and were standing there before someone arrived. The passenger broke one leg.			
CONCLUSION, ACTION TAKEN, OR REQUIRED			
DATE 07/22/2024	TITLE Aviation Safety Inspector	SIGNATURE  Federal Aviation Administration AHNNIE TRESPALACIOS SANTODOMINGO 2024.07.23 12:29:55 -04'00'	

