

ERA24LA313

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of submerged aircraft (Courtesy of FAA)



Photograph 2 - Impact damage - bent aircraft structure (Courtesy of FAA)



Photograph 3 - Impact damage - cracked forward hull (Courtesy of FAA)



Photograph 4 - Impact damage - bent aircraft structure (Courtesy of FAA)