

ERA24LA316

INVESTIGATIVE PHOTOS



Photograph 1 - Main wreckage (Courtesy of FAA)



Photograph 2 - Damaged empennage (Courtesy of FAA)



Photograph 3 - damaged left wing tip (Courtesy of FAA)



Photograph 4 - Damaged main landing gear (Courtesy of FAA)



Photograph 5 - Damaged main landing gear (Courtesy of FAA)