

ERA24LA325

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident damage right side lower fuselage (Courtesy of FAA)



Photograph 2 - Postaccident damaged main wheel attach fitting (Courtesy of FAA)