

ERA24LA332

INVESTIGATION PHOTOGRAPHS



Photograph 1 – Screen capture of midair collision video (Courtesy of FAA)



Photograph 2 – Screenshot of midair collision video (Courtesy of FAA)



Photograph 3 – N1041U wreckage at the accident site (Courtesy of FAA)



Photograph 4 – N1041U wreckage at the accident site (Courtesy of FAA)



Photograph 5 – N108CH after midair collision (Courtesy of FAA)



Photograph 6 – Damage to exhaust pipe of N108CH (Courtesy of FAA)



Photograph 7 - Damage to exhaust pipe of N108CH (Courtesy of FAA)



Photograph 8 – Damage to N108CH (Courtesy of FAA)