

ERA24LA335

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Main Wreckage (Courtesy of FAA)




Photograph 2 - Main Wreckage (Courtesy of FAA)




Photograph 3 - Spark plugs showing carbon fouling on cylinder No. 6. (Courtesy of Lycoming)



Photograph 4 - Engine front (Courtesy of Lycoming)



Photograph 5 - Engine back (Courtesy of Lycoming)



Photograph 6 - Fuel servo mounted to intake horn (Courtesy of NTSB)