

ERA24LA337

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of airplane (Courtesy of Pilot)



Photograph 2 - Damage to external longerons (Courtesy of FAA)



Photograph 3 - Damage to external longerons (Courtesy of FAA)



Photograph 4 - Shredded alternator belt (Courtesy of FAA)



Photograph 5 - Electrical power depiction after alternator failure and before battery failure in flight (Courtesy of Pilot)