

ERA24LA339

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane front postaccident (Courtesy of FAA)



Photograph 2 - Vertical stabilizer and rudder postaccident (Courtesy of FAA)