

ERA24LA345

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Digital Photograph From Owner. Front View of the Airplane Following Recovery



Photograph 2 - Digital Photograph From Owner. Left Side View of the Airplane Following Recovery



Photograph 3 - Digital Photograph From Owner. Right Side View of the Airplane Following Recovery



Photograph 4 - Digital Photograph From Owner. Right Side View of the Aft Empennage. Note the Wrinkle in the Fabric on the Lower Fuselage Tubing