

ERA24LA346

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to fuselage tubular structure (Courtesy of FAA)



Photograph 2 - Tubular structure deformation and thermal damage noted (Courtesy of FAA)



Photograph 3 - Thermal damage noted to fuselage (Courtesy of FAA)