

ERA24LA348

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane as its being recovered. (Courtesy of FAA)



Photograph 2 - Fuselage and engine compartment damage. (Courtesy of FAA)



Photograph 3 - Left wingtip damage. (Courtesy of FAA)



Photograph 4 - Overall view of airplane after recovery. (Courtesy of FAA)