

ERA24LA352

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of Pilot)



Photograph 2 - Tunnel Structure Substantial Damage (Courtesy of FAA)