

ERA24LA359

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Airplane being recovered from adjacent trees (Courtesy of FAA)



Photograph 2 - Damage to right wing (Courtesy of FAA)



Photograph 3 - Top of left wing - Fuel cap missing (Courtesy of FAA)



Photograph 4 - Fuel streaking aft of fuel cap - Left wing (Courtesy of FAA)



Photograph 5 - Top of right wing - Fuel cap intact (Courtesy of FAA)