

ERA24LA360

INVESTIGATION PHOTOGRAPHS




Photograph 1 - View of the Airplane's Right Side (Courtesy of FAA)



Photograph 2 - View of Airplane's Left Wing Damage (Courtesy of FAA)



Photograph 3 - Left Elevator Damage (Courtesy of FAA)



Photograph 4 - Broken Left Main Actuator Clevis (Courtesy of FAA)