



Photo 1 – View of Left Wing Underside (FAA)



Photo 2 – Top View of Left Wing Facing Inboard (FAA)



Photo 3 – View of Left Wing Leading Edge Damage (FAA)



Photo 4 – Upper Left Wing View Facing Towards Trailing Edge (FAA)



Photo 5 – Interior View of Left Wing Structure Forward of Aileron (FAA)