

ERA24LA377

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (FAA Photo)



Photograph 2 - Main Wreckage (FAA Photo)



Photograph 3 - Right Wing Damage (FAA Photo)



Photograph 4 - Right Wing Damage (FAA Photo)



Photograph 5 - Bent Right Main Landing Gear Extension Rod (FAA Photo)



Photograph 6 - Bent Right Main Landing Gear Extension Rod and Nose Gear Extension Rods (NTSB Photo)