

ERA24LA383

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of blue and white airplane with left wing bent upwards.
(Courtesy of FAA)**



**Photograph 2 - View of broken left landing gear strut
(Courtesy of FAA)**



**Photograph 3 - View of broken landing gear wheel assembly
(Courtesy of FAA)**