

ERA24LA383

ADDITIONAL INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of blue and white airplane with left wing bent upwards.
(Courtesy of FAA)**



**Photograph 2 - View of broken left landing gear strut
(Courtesy of FAA)**



**Photograph 3 - Close up of left landing gear strut fracture.
(Courtesy of FAA)**



**Photograph 4 - Close up of left landing gear strut assembly (side view) fracture.
(Courtesy of FAA)**



**Photograph 5 - Close up of left landing gear strut assembly fracture edges.
(Courtesy of FAA)**



**Photograph 6 - Close up of fractured wheel assembly.
(Courtesy of FAA)**