

ERA24LA388

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to rudder and vertical stabilizer (Courtesy of FAA)



Photograph 2 - Deformation and skin separation noted to right wing (Courtesy of FAA)



Photograph 3 - Buckling noted to fuselage (Courtesy of FAA)