

ERA24LA389

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right wing and nose wheel damage (Courtesy of FAA)



Photograph 2 - Right wing impact damage (Courtesy of FAA)



Photograph 3 - Right wing impact damage buckling(Courtesy of FAA)



Photograph 3 - Lower fuselage impact damage (Courtesy of FAA)