

ERA24LA390

INVESTIGATION PHOTOGRAPHS



Photograph 1 –View of airplane in wooded area showing damaged left wing. (Courtesy of FAA)



Photograph 2 – View of crushed engine cowling and fuselage (Courtesy of FAA)



Photograph 3 –View of buckled left wing root and upper fuselage damage. (Courtesy of FAA)