

ERA24LA392

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage From End of Runway (Courtesy of FAA)



Photograph 2 - Right Side Main Wreckage (Courtesy of FAA)



Photograph 3 - Left Wing Damage (Courtesy of FAA)




Photograph 4 - Runway Skid Marks (Courtesy of FAA)



Photograph 5 - Tire Tracks to Main Wreckage (Courtesy of FAA)



Photograph 6 - Engine Exam (Courtesy of Lycoming)



Photograph 7 - No. 3 Cylinder at Engine Exam (Courtesy of Lycoming)



Photograph 8 - No. 3 Cylinder Bore at Lycoming Materials Exam (NTSB Photo)



Photograph 9 - No. 3 Cylinder at Lycoming Materials Exam (NTSB Photo)



Photograph 10 - No 3. Exhaust Valve at Lycoming Materials Exam (NTSB Photo)



Photograph 11 - No. 3 Exhaust Valve Stem at Lycoming Materials Exam (NTSB Photo)