


ERA24LA399

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter at accident site (Source: Operator)



Photograph 2 - Damage to tail cone assembly (Source: Operator)



Photograph 3 - Damage to tail cone assembly (Source: Operator)