



Exemplar Truss




Side view showing the truss on an aircraft on the assembly line

Exemplar Truss



Side view pictures showing the truss on an aircraft on the assembly line



P/N SLS-030-056-015 Mechanical Truss Assembly
S/N MJ560621

Tailboom (tailcone) is being replaced due to the deformation of the doublers at the attachment point to the truss assembly, which is not repairable



505 S/N 65573 N945TC

Deformation of the doublers at the attachment point to the truss assembly



505 S/N 65573 N945TC

Deformation of the doublers at the attachment point to the truss assembly

