

ERA25FA143

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Empennage near end of wreckage path. (NTSB)



Photograph 2 - Wreckage path left to right. (NTSB)



Photograph 3 - Wreckage path looking towards empennage. (NTSB)



Photograph 4 - Propeller damage after recovery. (NTSB)