

ERA25LA011

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of VASP)



Photograph 2 - Left Wing Damage (Courtesy of VASP)



Photograph 3 - Throttle Cable Coupler (Courtesy of FAA)



Photograph 4 - Throttle Cable (Courtesy of FAA)



Photograph 5 - Throttle Arm (Courtesy of FAA)