

ERA25FA014

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site Overview (Courtesy of FAA)



Photograph 2 - Damage to the Fuselage from Right Side (Courtesy of FAA)



Photograph 3 - Damage to the Left Elevator (Courtesy of FAA)



Photograph 4 - Angle of Embankment Compared to the Airplane (Courtesy of FAA)