

ERA25LA016

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of left profile side of airplane at accident site.
(Courtesy of Leading Edge Investigations)**



Photograph 2 - View of airplane at accident site. (Courtesy of Leading Edge Investigations)



Photograph 3 - View of airplane in hangar. (Courtesy of Leading Edge Investigations)



Photograph 4 - Left wing damage from pole. (Courtesy of Leading Edge Investigations)