

ERA25LA021

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)




Photograph 2 - Buckled Nose Landing Gear (Courtesy of FAA)



Photograph 3 - Upper Fuselage Damage (Courtesy of FAA)



Photograph 4 - Wing Root Damage (Courtesy of FAA)



Photograph 5 - Nosewheel Steering Linkage (Courtesy of FAA)