

ERA25LA030

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of airplane looking aft showing damage to landing gear and airframe.
(Courtesy of FAA)**



Photograph 2 - Right landing gear damage. (Courtesy of FAA)