


ERA25LA031


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of FAA)



Photograph 2 - Structure wrinkling (Courtesy of FAA)



Photograph 3 - Floorboard wrinkling (Courtesy of FAA)



Photograph 4 - Floorboard wrinkling (Courtesy of FAA)