

ERA25LA041

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to fuselage tubular structure (Courtesy of FAA)



Photograph 2 - Deformation noted to right wing (Courtesy of FAA)



Photograph 3 - Split noted to fuel line (Courtesy of FAA)