

ERA25LA055

INVESTIGATIVE PHOTOS



Photograph 1 - Left lower wing damage (Courtesy of FAA)



Photograph 2 - Right upper wing damage (Courtesy of FAA)