

ERA25LA068

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Damage Right Wing (Courtesy of PEA)



Photograph 2 - Accident Damage Upper Forward Right Wing (Courtesy of PEA)



Photograph 3 - Accident Damage, Lower Forward Right Wing (Courtesy of PEA)



Photograph 4 - Postaccident Undercarriage (Courtesy of PEA)



Photograph 5 - Collapsed Right Main Gear Leg (Courtesy of PEA)



Photograph 6 - Right Main Gear Leg (Courtesy of PEA)



Photograph 7 - Right Wheel Well (Courtesy of PEA)