

ERA25LA074

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane overview (Source: FAA)



Photograph 2 - Airplane overview (Source: FAA)



Photograph 3 - Runway damage and airplane at accident site (Source: FAA)



Photograph 4 - Damage to tubular engine mount (Source: SkyBlue Aviation)



Photograph 5 - Damage to cabin floor (Source: SkyBlue Aviation)