


ERA25LA095

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage assessment (Courtesy of FAA)



Photograph 2 - View of left-wing root buckling (Courtesy of FAA)



Photograph 3 - View of right wing buckling (Courtesy of FAA)



Photograph 4 - View of the empennage buckling (Courtesy of FAA)